SIEMENS

Symbia T/Intevo Series

Update Instructions

MI006/14/S

Customer Advisory Notice: Motor Mounting Plate Update

-			C	•	
		Safety			
Update within		30 days			
Update by		☐ Remote	□ CSE	☐ Apps	
Intranet download available			☐ No		
Remote update		☐ Yes	⊠ No		
Materials for logistic update	required	☐ Yes	⊠ No		
Materials free of charge			☐ No	☐ No, credit if returned	
Return of parts		☐ Yes	⊠ No		
Customer application training		☐ Yes	⊠ No	Recommended	
Estimated completion time		.25 Hours(s)) Number of	CSE(s): 0	
Application training time		0 Hours(s))		
Scope					
Material number		ee Systems/Pr	oducts Affecte	d	
		See Systems/Products Affected			
Software version		See Prerequisites			
Related to Update Instructions		n.a.			
Change reference no.: Name: Department:	ECO 60 A. Agarv H CX CS			© Siemens, 2014 - Restricted - All documents may only be used by authorized personnel for rendering services on Siemens Healthcare Products. Any document in electronic form may be printed once Copy and distribution of electronic documents and hardcopies is prohibited. Offenders will be liable for damages. All other rights are reserved.	

Document: 10765085-EUA-000-01

Replaces: n.a.

ECO 600059

Document Date: July 03, 2014

liable for damages. All other rights are reserved.

Page 1 of 8

Copyright

"© Siemens, 2014" refers to the copyright of a Siemens entity such as Siemens Aktiengesellschaft - Germany, Siemens Shenzhen Magnetic Resonance Ltd. - China, Siemens Shanghai Medical Equipment Ltd. - China, Siemens Medical Solutions USA Inc. - USA, Siemens Healthcare Diagnostics Inc. - USA and/or Siemens Healthcare Diagnostics Products GmbH - Germany.

Document Version

Siemens reserves the right to change its products and services at any time. In addition, manuals are subject to change without notice. The hardcopy documents correspond to the version at the time of system delivery and/or printout. Versions to hardcopy documentation are not automatically distributed. Please contact your local Siemens office to order current version or refer to our website http://www.healthcare.siemens.com.

Disclaimer

Siemens provides this documentation "as is" without the assumption of any liability under any theory of law.

The service of equipment described herein is to be performed by qualified personnel who are employed by Siemens or one of its affiliates or who are otherwise authorized by Siemens or one of its affiliates to provide such services.

Assemblers and other persons who are not employed by or otherwise directly affiliated with or authorized by Siemens or one of its affiliates are not entitled to use this documentation without prior written authority.

Table of Contents

1.	General Information	4
1.1	Systems/Products Affected	4
1.2	ECO Number(s)	4
1.3	Reason for the Update	4
1.4	Prerequisites	4
1.5	Special Tools	4
2.	Material Information	5
2.1	Ordering Information	5
2.2	Content of Update Kit	5
2.3	Return of Parts	5
3.	Update	6
3.1	Work Steps	6
3.1.1	Preparation	6
3.1.2	Distribution	6
3.1.3	Final Check	6
3.2	Final Work Steps	7
3.3	Changes to Previous Version	7
4.	Completion Protocol	8
4.1	Reason for the Update	8
4.2	Protocol	8

1. General Information

1.1 Systems/Products Affected

Sub-IVK	Sub-IVK	Serial Number		
Description	Part Number	Start	Ending	
P15 Symbia T2	10165631	68001	68336, 68401,68402	
P15 Symbia T6	10165632	68501	68635	
P15 Symbia T16	10165633	69001	69114, 69491	
P18 Symbia T2	10611610	75001	75193	
P18 Symbia T6	10611611	68701	68801	
P18 Symbia T16	10611612	69201	69382	
P18 Intevo_2	10415136	89401	89418	
P18 Intevo_6	10415137	89901	88913	
P18 Intevo_16	10415138	90201	90216	

NOTE

This UI applies to all Symbia T series (PNs 10275007, 10275008, 10275009, 10275010) and Symbia Intevo systems (PNs 10764801, 10764802, 10764803 and 10764804) with P15/P18 CT gantry.

1.2 ECO Number(s)

Service ECO - 600059

1.3 Reason for the Update

Distribute Customer Safety Advisory Notice for the Motor Mounting Plate Update (MI005/14/S).

1.4 Prerequisites

One of the following systems with P15 or P18 Gantry:

 Symbia T (PN 10275007)
 Symbia Intevo Excel (PN 10764801)

 Symbia T2 (PN 10275008)
 Symbia Intevo 2 (PN 10764802)

 Symbia T6 (PN 10275009)
 Symbia Intevo 6 (PN 10764803)

 Symbia T16 (PN 10275010)
 Symbia Intevo 16 (PN 10764804)

Check the MED CS Intranet/Extranet for the latest version of this document (For Service -> Product Information -> MI Systems -> Updates -> 2014) or contact your local Siemens office if you don't have access to the Siemens Intranet/Extranet. IVK and Serial numbers affected are listed on MED CS Intranet/Extranet (CS Web Site).

1.5 Special Tools

N.A.

2. Material Information

2.1 Ordering Information

n.a.

2.2 Content of Update Kit

n.a.

2.3 Return of Parts

n.a.

3. Update

3.1 Work Steps

3.1.1 Preparation

3.1.1.1 Intranet Download

The required file: "MI006_14_S _customer_advisory_notice.zip" has to be downloaded from the Siemens Healthcare Intranet -> Customer Services.

- Go to the (CS Intranet start page, https://intranet.healthcare.siemens.com/cms/CS/en/)
- 2. Follow the path:

For Service -> Product Information -> MI -> SPECT Systems -> Downloads -> Customer Safety Letters

- 3. Select the year "UIs 2014"
- 4. Click the left mouse button on the file to be downloaded:

"MI006_14_S _customer_advisory_notice.zip"

- 5. Save the file on the hard drive D:\...
- 6. When finished saving, close the window.
- 7. Check the file with a standard anti-virus program

3.1.2 Work Steps

- 1. Open the zip file "MI006_14_S _customer_advisory_notice.zip".
- 2. Select the customer advisory notice in the correct language and unzip the corresponding file.
- 3. Print out the customer advisory notice.
- 4. Send the letter to the customer via certified mail and with a proof of delivery. (The reception needs to be acknowledged.)
- When you have received the proof of delivery report the update. See Final work Steps.

3.1.3 Final Check

n.a.

3.2 Final Work Steps

- 1. Fill out, and if needed, make a copy of the attached "Completion Protocol" and file it in the corresponding binder.
- 2. The update shall be reported by authorized personnel, either via an intranet application or by automated data transfer (only for countries connected via update handling interface).

3.3 Changes to Previous Version

n.a.

4. Completion Protocol

Customer Advisory Notice: Motor Mounting Plate Update

4.1 Reason for the Update

Distribute Customer Safety Advisory Notice for the Motor Mounting Plate Update (MI005/14/S).

4.2 Protocol

This update has been completed successfully. The customer has been informed of the benefits or improvements resulting from this update.

Customer:			
Customer No.:		Func. Location:	
Material No. of the system:		Serial number of the system:	
Notification:			
Remark:			
Remark:			
Country:		Site:	
Performed By:		Telephone:	
Date:		Signature:	
NOTE	After completing the update, it in the corresponding Syste	• •	



Molecular Imaging

Customer Safety Advisory Notice (CAN 006-2014)

To: Director of the Radiology Department
Director of the Nuclear Medicine Department
Risk Management Officer
Users of Symbia T camera systems
Users of Symbia Intevo camera systems

Re: Symbia T Series and Symbia Intevo camera system with rubber component on the motor mounting plate

Dear Valued Siemens Customer,

You are receiving this letter because you have been identified as owning a Symbia T Series or Symbia Intevo camera system that may be affected by a hardware problem within the CT gantry.

This letter serves as notification of an upcoming field correction. The field correction is required because we recently detected a rubber isolator with unfavorable aging properties. The function of this rubber isolator, which is situated within the rotate motor mounting assembly, may degrade over time and may impact motor support. We have not received any reports of injury with the Symbia T or Symbia Intevo camera systems as a result of this problem.

When could this problem occur and what is the potential risk?

In rare cases, when unfavourable ageing has occurred, the rubber isolator may break and cause loss of support for the rotate motor. This event does not pose a hazard by itself but could lead to a rupture of the drive belt which in turn could damage the gantry covers and make contact with the patient. While we expect any subsequent injury to be minor, the possibility of a serious injury does exist if the belt makes contact with the patient.

What should you do until the repair is performed?

Based on our investigation, you can continue to use your system while waiting for the field correction to be scheduled and performed. If you are experiencing abnormal noise or vibration, discontinue use immediately and please contact your service engineer.

Your local service engineer will contact you and perform the mounting plate replacement by December 2014. This new mounting plate includes improved rubber components and a backup device to ensure trouble free operation in the future.



Please ensure that this safety advisory is placed in the System Owner's Manual. If you rely on non-Siemens service, please share this letter with your support staff. If you have sold this equipment and it is no longer in your possession, we kindly ask that you forward this safety notice to the new owner of this equipment. Please inform us about the new owner of the equipment.

If you have any questions regarding this important advisory notice, please contact your local Service representative at the contact numbers provided below.

America: 1-800-888-7436

rein Stal

Europe, Middle East, and Africa: +49 9131 940 4000

Asia and Australia: +86 (21) 3811 2121

Sincerely,

Matt Shah

Vice President, Quality, Regulatory, and EHS

Molecular Imaging CAN006-2014