

October 01, 2014

URGENT: FIELD SAFETY NOTICE
RENASYS™ EZ, RENASYS™ EZ PLUS, RENASYS™ EZ MAX, RENASYS™ GO

Customer Name
Device Name
Street Address
City, State, Zip Code

Dear Device Customer,

Following discussions with various Competent Authorities in the EU and a recent review of post marketing surveillance information regarding our RENASYS™[®] range of Negative Pressure Wound Therapy (“NPWT”) devices (‘RENASYS™ devices), Smith & Nephew are issuing a Field Safety Notice (‘FSN’) concerning RENASYS™ devices. The purpose of the FSN is:

1. To inform users of changes that have been implemented on RENASYS™ devices and to instruct users to discard certain RENASYS™ consumables.
2. To announce the implementation of amended Instructions For Use (‘IFU’) for RENASYS™ devices, to remind customers of the importance of patient monitoring requirements during negative pressure wound therapy.

This FSN has been agreed by relevant Competent Authorities in the EU.

1. Product Changes

Smith & Nephew implemented a number of changes to RENASYS™ devices on the basis of customer feedback ('the changes'). Table 1 below sets out:

- Descriptions of the product changes,
- The rationale for the product changes,
- The Customer action required

TABLE 1

Applicable RENASYS™ System	Description of Product Change	Rationale for the Product Change	Customer action												
EZ / EZ Plus	Bacterial Overflow Guard material change	The material was changed to allow easier insertion to the RENASYS EZ / EZ Plus devices	<p>In the event that users still have RENASYS™ devices with lot numbers that pre-date the changes in inventory (the detailed lot numbers affected are set out below), further action is required: more specifically, users are required to discard any Canisters remaining in their inventory</p> <table border="1" data-bbox="656 991 1414 1390"> <thead> <tr> <th data-bbox="662 999 1130 1024">Product Description / Product Code</th> <th data-bbox="1136 999 1408 1024">Affected Lot Numbers</th> </tr> </thead> <tbody> <tr> <td data-bbox="662 1033 1130 1100">RENASYS™ EZ Plus Canister 800ml with solidifier / 66800912</td> <td data-bbox="1136 1033 1408 1100">All lots < M400300</td> </tr> <tr> <td data-bbox="662 1108 1130 1176">RENASYS™ EZ Plus Canister 250ml with solidifier / 66800913</td> <td data-bbox="1136 1108 1408 1176">All lots < M400300</td> </tr> <tr> <td data-bbox="662 1184 1130 1251">RENASYS™ EZ Plus Canister 800ml with without solidifier / 66801066</td> <td data-bbox="1136 1184 1408 1251">All lots < M400300</td> </tr> <tr> <td data-bbox="662 1260 1130 1327">RENASYS™ EZ Plus Canister 800ml with solidifier / 66800423</td> <td data-bbox="1136 1260 1408 1327">All lots < M400300</td> </tr> <tr> <td data-bbox="662 1335 1130 1402">RENASYS™ EZ Plus Canister 250ml with solidifier / 66800058</td> <td data-bbox="1136 1335 1408 1402">All lots < M400300</td> </tr> </tbody> </table> <p>For ease of identification of affected lots for the RENASYS EZ Plus Canisters: The lot number follows a sequential numbering system, with the letter bearing no factor on this sequence. Therefore all lots with a number lower than 400300 are affected.</p>	Product Description / Product Code	Affected Lot Numbers	RENASYS™ EZ Plus Canister 800ml with solidifier / 66800912	All lots < M400300	RENASYS™ EZ Plus Canister 250ml with solidifier / 66800913	All lots < M400300	RENASYS™ EZ Plus Canister 800ml with without solidifier / 66801066	All lots < M400300	RENASYS™ EZ Plus Canister 800ml with solidifier / 66800423	All lots < M400300	RENASYS™ EZ Plus Canister 250ml with solidifier / 66800058	All lots < M400300
Product Description / Product Code	Affected Lot Numbers														
RENASYS™ EZ Plus Canister 800ml with solidifier / 66800912	All lots < M400300														
RENASYS™ EZ Plus Canister 250ml with solidifier / 66800913	All lots < M400300														
RENASYS™ EZ Plus Canister 800ml with without solidifier / 66801066	All lots < M400300														
RENASYS™ EZ Plus Canister 800ml with solidifier / 66800423	All lots < M400300														
RENASYS™ EZ Plus Canister 250ml with solidifier / 66800058	All lots < M400300														

All RENASYS™ Systems	Soft Port Aperture change	<p>Size of the aperture was changed in order to:</p> <p>(i) allow easier alignment of the Soft Port and the hole cut in the transparent film;</p> <p>(ii) improve the management of viscous fluid</p>	<p>In the event that users still have RENASYS™ devices with lot numbers that pre-date the changes in inventory (the detailed lot numbers affected are set out below), further action is required: more specifically, users are required to discard any Canisters or Soft Ports remaining in their inventory</p> <table border="1" data-bbox="691 478 1385 1241"> <thead> <tr> <th data-bbox="691 478 1073 552">Product Description / Product Code</th> <th data-bbox="1073 478 1385 552">Affected Lot Numbers</th> </tr> </thead> <tbody> <tr> <td data-bbox="691 552 1073 625">RENASYS™ -F Small with Soft Port / 66800794</td> <td data-bbox="1073 552 1385 625">All lots < 2013011828</td> </tr> <tr> <td data-bbox="691 625 1073 699">RENASYS™ -F Medium with Soft Port / 66800795</td> <td data-bbox="1073 625 1385 699">All lots < 2013010125</td> </tr> <tr> <td data-bbox="691 699 1073 772">RENASYS™ -F Large with Soft Port / 66800796</td> <td data-bbox="1073 699 1385 772">All lots < 2013011692</td> </tr> <tr> <td data-bbox="691 772 1073 846">RENASYS™ -F Extra Large with Soft Port / 66800797</td> <td data-bbox="1073 772 1385 846">All lots < 2013011830</td> </tr> <tr> <td data-bbox="691 846 1073 919">RENASYS™ Soft Port Kit / 66800799</td> <td data-bbox="1073 846 1385 919">All lots < 2013010311</td> </tr> <tr> <td data-bbox="691 919 1073 951">Abdominal Kit / 66800980</td> <td data-bbox="1073 919 1385 951">All lots < 2013010287</td> </tr> <tr> <td data-bbox="691 951 1073 1024">RENASYS™ -G Small with Soft Port / 66800933</td> <td data-bbox="1073 951 1385 1024">All lots < 2013020417</td> </tr> <tr> <td data-bbox="691 1024 1073 1098">RENASYS™ -G Medium with Soft Port / 66800934</td> <td data-bbox="1073 1024 1385 1098">All lots < 2013020209</td> </tr> <tr> <td data-bbox="691 1098 1073 1171">RENASYS™ -G Large with Soft Port / 66800935</td> <td data-bbox="1073 1098 1385 1171">All lots < 2013020382</td> </tr> <tr> <td data-bbox="691 1171 1073 1241">RENASYS™ -G Extra Large with Soft Port / 66800936</td> <td data-bbox="1073 1171 1385 1241">All lots < 2013020501</td> </tr> </tbody> </table> <p>For ease of identification of affected Soft Port Kits, the following text explains how the lot number is structured:</p> <p>E.g. Lot number 2013010287 → [2013] [01] [02] [87]</p> <p>The digits in the first bracket denotes the year of manufacturer: 2013</p> <p>The digits in the second bracket denotes the Month: January</p> <p>The digits in the third bracket denotes the day of the Month: 2nd</p> <p>The digits in the fourth bracket denotes the sequential batch number: 87th batch produced</p>	Product Description / Product Code	Affected Lot Numbers	RENASYS™ -F Small with Soft Port / 66800794	All lots < 2013011828	RENASYS™ -F Medium with Soft Port / 66800795	All lots < 2013010125	RENASYS™ -F Large with Soft Port / 66800796	All lots < 2013011692	RENASYS™ -F Extra Large with Soft Port / 66800797	All lots < 2013011830	RENASYS™ Soft Port Kit / 66800799	All lots < 2013010311	Abdominal Kit / 66800980	All lots < 2013010287	RENASYS™ -G Small with Soft Port / 66800933	All lots < 2013020417	RENASYS™ -G Medium with Soft Port / 66800934	All lots < 2013020209	RENASYS™ -G Large with Soft Port / 66800935	All lots < 2013020382	RENASYS™ -G Extra Large with Soft Port / 66800936	All lots < 2013020501
Product Description / Product Code	Affected Lot Numbers																								
RENASYS™ -F Small with Soft Port / 66800794	All lots < 2013011828																								
RENASYS™ -F Medium with Soft Port / 66800795	All lots < 2013010125																								
RENASYS™ -F Large with Soft Port / 66800796	All lots < 2013011692																								
RENASYS™ -F Extra Large with Soft Port / 66800797	All lots < 2013011830																								
RENASYS™ Soft Port Kit / 66800799	All lots < 2013010311																								
Abdominal Kit / 66800980	All lots < 2013010287																								
RENASYS™ -G Small with Soft Port / 66800933	All lots < 2013020417																								
RENASYS™ -G Medium with Soft Port / 66800934	All lots < 2013020209																								
RENASYS™ -G Large with Soft Port / 66800935	All lots < 2013020382																								
RENASYS™ -G Extra Large with Soft Port / 66800936	All lots < 2013020501																								

All RENASYS™ systems	Soft Port backing paper slit addition	To allow easier application of the Soft Port dressing	<p>In the event that users still have RENASYS™ devices with lot numbers that pre-date the changes in inventory (the detailed lot numbers affected are set out below), further action is required: more specifically, users are required to discard any Canisters or Soft Ports remaining in their inventory</p> <table border="1" data-bbox="691 478 1416 1241"> <thead> <tr> <th data-bbox="691 478 1073 552">Product Description / Product Code</th> <th data-bbox="1079 478 1416 552">Affected Lot Numbers</th> </tr> </thead> <tbody> <tr> <td data-bbox="691 560 1073 625">RENASYS™ -F Small with Soft Port / 66800794</td> <td data-bbox="1079 560 1416 625">All lots < 2013011828</td> </tr> <tr> <td data-bbox="691 634 1073 699">RENASYS™ -F Medium with Soft Port / 66800795</td> <td data-bbox="1079 634 1416 699">All lots < 2013010125</td> </tr> <tr> <td data-bbox="691 707 1073 772">RENASYS™ -F Large with Soft Port / 66800796</td> <td data-bbox="1079 707 1416 772">All lots < 2013011692</td> </tr> <tr> <td data-bbox="691 781 1073 846">RENASYS™ -F Extra Large with Soft Port / 66800797</td> <td data-bbox="1079 781 1416 846">All lots < 2013011830</td> </tr> <tr> <td data-bbox="691 854 1073 919">RENASYS™ Soft Port Kit / 66800799</td> <td data-bbox="1079 854 1416 919">All lots < 2013010311</td> </tr> <tr> <td data-bbox="691 928 1073 951">Abdominal Kit / 66800980</td> <td data-bbox="1079 928 1416 951">All lots < 2013010287</td> </tr> <tr> <td data-bbox="691 959 1073 1024">RENASYS™ -G Small with Soft Port / 66800933</td> <td data-bbox="1079 959 1416 1024">All lots < 2013020417</td> </tr> <tr> <td data-bbox="691 1033 1073 1098">RENASYS™ -G Medium with Soft Port / 66800934</td> <td data-bbox="1079 1033 1416 1098">All lots < 2013020209</td> </tr> <tr> <td data-bbox="691 1106 1073 1171">RENASYS™ -G Large with Soft Port / 66800935</td> <td data-bbox="1079 1106 1416 1171">All lots < 2013020382</td> </tr> <tr> <td data-bbox="691 1180 1073 1245">RENASYS™ -G Extra Large with Soft Port / 66800936</td> <td data-bbox="1079 1180 1416 1245">All lots < 2013020501</td> </tr> </tbody> </table> <p data-bbox="691 1287 1398 1392">For ease of identification of affected Soft Port Kits, the following text explains how the lot number is structured:</p> <p data-bbox="691 1400 1373 1434">E.g. Lot number 2013010287 → [2013] [01] [02] [87]</p> <p data-bbox="691 1482 1325 1549">The digits in the first bracket denotes the year of manufacturer: 2013</p> <p data-bbox="691 1558 1370 1625">The digits in the second bracket denotes the Month: January</p> <p data-bbox="691 1633 1377 1701">The digits in the third bracket denotes the day of the Month: 2nd</p> <p data-bbox="691 1709 1398 1776">The digits in the fourth bracket denotes the sequential batch number: 87th batch produce</p>	Product Description / Product Code	Affected Lot Numbers	RENASYS™ -F Small with Soft Port / 66800794	All lots < 2013011828	RENASYS™ -F Medium with Soft Port / 66800795	All lots < 2013010125	RENASYS™ -F Large with Soft Port / 66800796	All lots < 2013011692	RENASYS™ -F Extra Large with Soft Port / 66800797	All lots < 2013011830	RENASYS™ Soft Port Kit / 66800799	All lots < 2013010311	Abdominal Kit / 66800980	All lots < 2013010287	RENASYS™ -G Small with Soft Port / 66800933	All lots < 2013020417	RENASYS™ -G Medium with Soft Port / 66800934	All lots < 2013020209	RENASYS™ -G Large with Soft Port / 66800935	All lots < 2013020382	RENASYS™ -G Extra Large with Soft Port / 66800936	All lots < 2013020501
Product Description / Product Code	Affected Lot Numbers																								
RENASYS™ -F Small with Soft Port / 66800794	All lots < 2013011828																								
RENASYS™ -F Medium with Soft Port / 66800795	All lots < 2013010125																								
RENASYS™ -F Large with Soft Port / 66800796	All lots < 2013011692																								
RENASYS™ -F Extra Large with Soft Port / 66800797	All lots < 2013011830																								
RENASYS™ Soft Port Kit / 66800799	All lots < 2013010311																								
Abdominal Kit / 66800980	All lots < 2013010287																								
RENASYS™ -G Small with Soft Port / 66800933	All lots < 2013020417																								
RENASYS™ -G Medium with Soft Port / 66800934	All lots < 2013020209																								
RENASYS™ -G Large with Soft Port / 66800935	All lots < 2013020382																								
RENASYS™ -G Extra Large with Soft Port / 66800936	All lots < 2013020501																								

RENASYS™ EZ / EZ Plus	800ml canisters	The PVC tubing material was changed to prevent the deformation of the canister inlet port	In the event that users still have RENASYS™ devices with lot numbers that pre-date the changes in inventory (the detailed lot numbers affected are set out below), further action is required: more specifically, users are required to discard any Canisters or Soft Ports remaining in their inventory	
			Product Description / Product Code	Affected Lot Numbers
			RENASYS™ Ez Plus Canister 800ml / 66800912	All lots < M400140
			RENASYS™ Ez Plus Canister 800ml without solidifier / 66801066	All lots < M400140
			RENASYS™ Ez Plus Canister 800ml / 66800423	All lots < M400140
		<p>For ease of identification of affected lots for the RENASYS EZ Plus Canister 800ml</p> <p>The lot number follows a sequential numbering system, with the letter bearing no factor on this sequence. Therefore all lots with a number lower than 400140 are affected.</p>		

2. Amendments to the IFU

Smith & Nephew hereby announces changes to the IFU for the RENASYS™ devices listed in Table 2.

TABLE 2

Product Codes	Product Description
66800164, 66801244, 66801496	RENASYS™ GO
66800059	RENASYS™ EZ
66800697, 66801243	RENASYS™ EZ PLUS
66801309, 66801310	RENASYS™ EZ MAX

Smith & Nephew has become aware of cases where a blockage can occur beneath the RENASYS™ devices film dressing, reducing fluid removal from the dressing through the port and into the canister. Notably, heavy wound exudate, viscous wound exudate, exudate with sediment or when blood is present can lead to the saturation of the wound filler, and to blockage formation. This situation can arise with both gauze and foam wound fillers.

If a blockage occurs in this way, the exudate may accumulate or “pool” beneath the film dressing, which creates a potential risk of maceration to surrounding tissue and can eventually, cause the dressing to lift and allow exudate to leak from the wound.

Smith & Nephew determined that RENASYS™ devices may not be able to detect such blockages if the vacuum between the pump and the dressing is still present. In these circumstances, RENASYS™ devices may not alarm to alert the user to the presence of the blockage.

Even in cases where the dressing has visibly lifted, it is still possible that the device may not alarm, as a vacuum is still being maintained between the dressing, the port and the device.

On the basis of these observations, Smith & Nephew will amend the IFUs applicable for the RENASYS™[®] range of products, to re-emphasise the importance of patient monitoring requirements. The IFU amendments will remind customers that the dressing is to be checked regularly to ensure that pooling is not occurring beneath the dressing and remind users not to rely solely on the device alarms to ensure that therapy is being effectively delivered.

Smith & Nephew expects that the revised instructions will be available for all users by the **30th November, 2014**. In the interim, this letter will provide you with the essential elements of the revised IFU as soon as possible.

Please note that you are required to complete and return the attached *Acknowledgement and Receipt Form* by October 24, 2014, **even if you do not have any product on hand**.

Should you have any questions in relation to this FSN including product replacements, please do not hesitate in contacting the Smith & Nephew via email Advice.Healthcare@smith-nephew.com or telephone UK (0800) 9155 394, IRE (1800) 30 36 22.

The revised IFU will include the following “Important information” section:

Important information

Monitoring NPWT

Carefully monitor the patient, device and dressing frequently, to determine if there are any signs of bleeding, exudate accumulation (pooling), infection, maceration, or loss of Negative Pressure Wound Therapy (NPWT). The frequency should be determined by the clinician based on individual characteristics of the patient and wound. NPWT devices are not designed to detect or issue an alarm condition based on the presence of bleeding or pooling. These conditions may only be detected by frequent monitoring.

Special attention to the risks of bleeding or loss of NPWT should be considered when prescribing for use in the Home Environment.

NPWT may be impacted by various conditions related to system configuration, set-up and individual characteristics of the patient and wound (e.g. exudate characteristics, patient anatomy). Alignment of the port to the opening in the drape, use of a bridging technique and choice of dressing configuration based on wound characteristics may impact NPWT vacuum delivery over the course of therapy. Exudate volume, viscosity and consistency may influence fluid removal or occlusion formation. A full canister, incorrect canister orientation and device/tubing height relative to the wound can contribute to loss of NPWT and exudate accumulation within the wound, which could lead to maceration, infection, or unrecognised bleeding.

Monitor the wound for infection and ensure that all wound filler is removed at each dressing change to reduce the risk of infection.

Skin grafts should be closely monitored to ensure NPWT is being delivered.

The revised IFU will also include the following “Cautions” for leak alarms and blockage alarms:

Caution – Lack of Blockage alarm:

If partial blockage occurs, the change in pressure status detected by device may not be significant enough to trigger alarm activation. Over time if blockage reaches point of full occlusion, complete blockage alarm will activate.

Blockage formation within the wound dressing will not be detected by the system as it has occurred outside of the monitored vacuum circuit, but can affect pressure status at the wound. Appropriately frequent monitoring of wound dressing is recommended to confirm adequate delivery of therapy.

In the event of heavy or viscous drainage, drainage with sediment or when blood is present, regular monitoring and more frequent dressing changes may be required.

If a complete blockage is present in the system, but an air leak occurs between blockage and device, the alarm may not activate. Ensure all connections are secure and no air leaks are present in system.

Potential sources of air leaks include:

- Misplaced or worn O-ring on the RENASYS GO device inlet port, located between the device and canister
- Partially inserted in-line bacterial overflow guard on the RENASYS EZ/EZ PLUS/EZ MAX devices
- Tear in Soft Port
- Misplaced or worn O-ring within the quick click connector (between the Soft Port and canister tubing)
- Cracked or damaged canister

Caution – Lack of Leak alarm:

Under specific circumstances, a significant air leak may occur in system without device activating a high flow/leak alarm. This may be due to partial blockage between source of air leak and device, prohibiting detection of the leak by device, resulting in no alarm activation.

Potential sources of blockage include:

- Physical occlusion in wound dressing (coagulated blood or purulent material in filler, compacted filler, high volume viscous fluid)
- Physical occlusion in tubing (kink in canister tubing, clot in tubing)
- Soft Port aperture misaligned to dressing opening.

Check wound dressing regularly to ensure it is fully compressed and firm to the touch.

STEPS FOR FIELD SAFETY NOTICE

The *Acknowledgement, Receipt and Confirmation of Disposal Form* attached to this letter must be completed and returned even if you do not have any product in your inventory.

THIS FIELD SAFETY NOTICE DOES NOT REQUIRE ANY RETURN OF RENASYS™ NPWT PRODUCTS.

THIS FIELD SAFETY NOTICE REQUIRES CUSTOMERS TO DISCARD AFFECTED RENASYS™ NPWT PRODUCTS

DO NOT DISCONTINUE TREATMENT OR RETURN ANY PRODUCT

- 1. Identify users of RENASYS™ NPWT systems.** Please identify all users of Smith & Nephew RENASYS™ range of NPWT systems, who may need to be made aware of the enhancements to the IFU and Product changes contained in this Field Safety Corrective Action. Users may be healthcare professionals, home care workers or patients.
- 2. Provide copies of this notice to all identified users as soon as is reasonably practicable.**
- 3. Complete the *Acknowledgement, Receipt and Confirmation of Disposal Form*.** Complete and return the enclosed *Acknowledgement, Receipt and Confirmation of Disposal Form* as soon as reasonably possible. If necessary, your Smith & Nephew sales representative can assist you in completing the form.
- 4.** Please return the completed form via email Advice.Healthcare@smith-nephew.com , F: 44(0) 1482 222 211, or by post using the pre-paid envelope provided.

Approved By:

David Wright
Regulatory & Quality Manager
Advanced Wound Care, UK & Ireland

IMPORTANT - MEDICAL DEVICE FIELD SAFETY NOTICE RESPONSE
Acknowledgement, Receipt and Confirmation of Disposal Form

Response is required within 15 days

Customer Information:

Customer Name
 Street Address
 Town, State, Zip Code

RENASYS™ EZ, RENASYS™ EZ PLUS, RENASYS™ EZ MAX, RENASYS™ GO

I have read and understood the information contained in this letter and have distributed copies to all relevant users, as defined in the instructions.

PLEASE SELECT THE APPROPRIATE OPTION IN TABLE A

Table A

I have checked inventory for the affected products listed in the Field Safety Notice and confirm zero inventory remaining	<input type="checkbox"/>
I have checked inventory for the affected products listed in the Field Safety Notice and can confirm inventory remaining	<input type="checkbox"/>
[IF YOU TICK THIS BOX PLEASE ALSO COMPLETE TABLE B]	

Table B - ONLY COMPLETE THIS TABLE IF YOU HAVE IDENTIFIED AFFECTED PRODUCTS LISTED IN THE FIELD SAFETY NOTICE IN YOUR LOCATION

Product description	Lot number	Quantity of product discarded

[ADD ADDITIONAL ROWS IF REQUIRED]

Please provide any additional information, if applicable.

Name	
Signature	
Title	
Telephone	
Email address	

- PLEASE EMAIL, FAX or POST the COMPLETED RESPONSE FORM TO:** Advice.Healthcare@smith-nephew.com , F: 44(0) 1482 222 211, or post using the pre-paid envelope provided.