

Urgent Field Safety Notice (FSN)

Product Name: DePuy Synthes - ATTUNE® Intuition Distal Femoral Jig

FSCA-identifier: HHE-103070405

Type of Action: Field Safety Notice

Date: Oct 2014

Attention: Trust Chief Executives, the Clinical Director-Orthopaedic Department, the Orthopaedic Theatre Manager, the Safety Liaison Officer, General Managers – Private Sector Hospitals

Type of device: Instrument used for Orthopaedic Knee Joint Replacement

Model names: DePuy Synthes - ATTUNE® Intuition Distal Femoral Jig

Part numbers: 254400521 and 254400520 (all lots)

DePuy Orthopaedics, Inc. is issuing a Field Safety Notice/device correction for all lots of the ATTUNE® Intuition Distal Femoral Jig (Part Nos. 254400521 and 254400520). This correction is being issued because if the metal pin bushing is overloaded, there is the potential for partial or full displacement of the metal pin bushing along with fracture of the plastic around the metal pin bushing. If the plastic around the metal pin bushing fractures, there is the potential for fragments of the fractured plastic to be left in the patient.

The company is advising an inspection of specific lots of the ATTUNE® Intuition Distal Femoral Jig (Part numbers 254400521 and 254400520), as those instruments may be assembled incorrectly. Theatre Staff and persons involved with the Cleaning and Reprocessing of the device are requested to inspect all inventory for specific lots see “Inspection and Swap-Out of Femoral Jigs for Incorrect Assembly” on Page 2. In the instance that a device is found to be assembled incorrectly it is requested to be returned and exchanged for a correctly assembled device.

Affected Instruments:

Part numbers: 254400521 and 254400520

Lot Numbers: All Lots for Device Correction. See Attachment A for lot specific inspection/swap-out.

Intended Use:

The distal femoral jig (Figure 1) allows the surgeon to position the distal cutting block on the anterior condyles at the desired varus / valgus angle and distal resection depth. Proximal-Distal stability of the instrument is achieved by inserting the Intramedullary Rod into the Femoral IM Canal. Pinning the jig on the distal femoral condyles is optional.

Reason for Device Correction with Lot Specific Swap-Out

During the company’s complaints investigation, it was determined that the metal pin bushing has the potential to be displaced during use and therefore allow plastic debris to break from the instrument. This is potentially caused by excessive loading applied during pinning of the jig to the distal femoral condyles. The complaint rate of the bushings partially or fully displacing is 0.018%.




Figure 1: ATTUNE® Intuition Distal Femoral Jig

A separate issue was also discovered in which the metal pin bushing was incorrectly assembled during the manufacturing process in some instruments. Metal pin bushings have been displaced in both correctly and incorrectly assembled bushings. Subject to the following guidance and the medical professional’s discretion, use of the jig with incorrectly assembled bushings remains acceptable to continue to produce the desired outcome.


Inspection and Swap-Out of Femoral Jigs for Incorrect Assembly

Until the instrument swap-out is completed, incorrectly assembled jigs may continue to be used at the discretion of the medical professional. As previously stated, bushings have failed on correctly assembled bushings as well. Therefore, in deciding to continue to use the jig, the medical professional should consider that pinning the jig on the distal femoral condyles is optional and adhere to the information provided in the Medical Professional notice.

Inspecting the ATTUNE® Intuition Distal Femoral Jig: Figures 2 and 3 depict correctly versus incorrectly assembled metal pin bushings. Use this as a guide for inspecting affected instruments.

Figure 2: The correctly assembled jig will have the smaller diameter (5.50 mm) end of the metal pin bushing on the jig’s top side. The incorrectly assembled jig will have the larger diameter (6.50 mm) end of the metal pin bushing on the jig’s top side. The incorrectly assembled jig has a wall thickness of the black plastic surrounding the bushing which is considerably thinner than the wall thickness of the bushing.

Correctly Assembled



Incorrectly Assembled




Figure 2: Top of Jig – Comparison of Correctly Assembled vs. Incorrectly Assembled (Inverted Bushing)

Figure 3: The correctly assembled jig will have the larger diameter (6.50 mm) end of the metal pin bushing on the jig’s bone side (bottom side). The incorrectly assembled jig will have the smaller diameter (5.50 mm) end of the metal pin bushing on the jig’s bone side (bottom side).

Correctly Assembled



Incorrectly Assembled



Figure 3: Bottom of Jig (bone side) – Comparison of Correctly Assembled vs. Incorrectly Assembled (Inverted Bushing)

Device Correction Information

To reduce the risk of the metal pin bushing displacing and possibly damaging the plastic, the company recommends instrument users follow directions provided in the surgical technique titled, “DePuy Synthes Joint Reconstruction ATTUNE® Knee System Surgical Technique” (Cat. No.0612-10-512). Specifically:

1. Refer to Page 8 of the surgical technique. This section highlights that headed pins should not be over tightened against surfaces of uncut bone. It is recommended to not continue to drive the headed pin once the head contacts the bushing.

“Headed pins are best used to secure blocks against a flat surface such as cut bone, however, if used on uncut bone with a curved surface, be careful that the Headed Pins are not over tightened as this can lead to tilting and malalignment of the block.”




Figure 4: Images of Correct vs. Incorrect (over tightened) Pinning from Page 8 of the “DePuy Synthes Joint Reconstruction ATTUNE® Knee System Surgical Technique” (Cat. No. 0612-10-512)

2. Refer to Page 13 of the surgical technique. This section highlights that the use of the pins in the distal resection plate is optional.

“... The Jig may be pinned temporarily using pin holes in the distal resection plate.”

Units Affected

There have been 3,082 affected devices distributed worldwide. This device correction and swap-out does not affect any other instruments.

Depth of Device Correction with Lot Specific Inspection and Swap-Out

This device correction with lot specific inspection and swap-out provides instructions for notifying Medical Professionals (surgeon users and hospitals /medical facilities) who used/purchased the ATTUNE® Intuition Distal Femoral Jig (Part. Nos. 254400521 and 254400520) and 2) instructions to inspect specific lots.

Clinical Implications

If the metal pin bushing displaces, damages, or fractures the plastic and plastic debris is not removed from the patient, clinical implications may include:

- Adverse tissue reaction if the broken piece of the plastic was not removed, the surrounding tissue may become irritated
- Poor joint mechanics if the remaining fragment is left in the joint space
- Pain

The clinical implications above may potentially require revision surgery. Following are general examples of possible risks/hazards of revision surgery:

1. Infection
2. Additional scarring
3. Neural and vascular damage
4. Additional pain to the patient
5. Functional problems resulting from items 1 – 4 above
6. Anesthesia-associated risks

Transmission of this Field Safety Notice:

This notice has been sent to you as records indicate that your organization/hospital has purchased the ATTUNE® Intuition Distal Femoral Jig

This notice needs to be passed on to all those who need to be aware within your organisation or to any organisation where these products may have been transferred.

To confirm receipt of this FSN please complete and return the acknowledgement in Attachment B.

For any enquiries about the ATTUNE® Intuition Distal Femoral Jig contact:

Alan O' Sullivan
Recall Co-Ordinator
e-mail – aosulliv@its.jnj.com
Tel no - +353 21 4914149

This FSN has been notified to the appropriate Regulatory Agency.

Sincerely,



Simon Sinclair PhD MB BChir
Worldwide Vice President, Strategic Medical Affairs

Attachment A: Lots to Inspect for Incorrect Assembly

Cat. No.	DePuy Synthes Lot No:	MFG Lot No:
254400520	ABC22844	C22844
	ABC22845	C22845
	ABC34279	C34279
	ABC34280	C34280
	ABC4107	C4107
	ABC4108	C4108
	ABC4112	C4112
	ABC4113	C4113
	ABC50741	C50471
254400521	ABB13662	B13662
	ABB19116	B19116
	ABB19117	B19117
	ABB19118	B19118
	ABB35392	B35392
	ABB35393	B35393
	ABB39835	B39835
	ABB41384	B41384
	ABB46872	B46872
	ABB49200	B49200
	ABB50724	B50724
	ABB55749	B55749
	ABB63598	B63598
	ABB66346	B66346
	ABB72107	B72107
	ABB77183	B77183
	ABB79390	B79390
	ABB79391	B79391
	ABB80712	N80712
	ABC17165	C17165
ABC5023	C5023	

Attachment B:

**This Letter acknowledges receipt of the Field Safety Notice related to ATTUNE® Intuition
Distal Femoral Jig**

(Please check as appropriate)

Yes, I have received the FSN

Please fax or e-mail this completed document to
[INSERT DePuy Marketing Company/Affiliate contact details]

Print Name: _____

Signature

Hospital Name

City

Country

Telephone Number or e-mail address