

**Notice Information: - Advisory
01 April 2011**

Part 1. Product Information

- a) Title:
- b) Product Name/Type:
- c) Reference:
- d) Manufacturer/Supplier:

Part 2. Target Audience

- a) Target Audience:

Part 3. Problem/Issue

a) Problem/Issue:

BHM Medical Inc. has become aware that a number of hoists may have been fitted with an incorrect power cable on the control box.

Part 4. Background Information

a) Background Information:

BHM Medical Inc. has confirmed that a number of hoists manufactured from May 2004 to March 2006 inclusive may have been fitted incorrectly with a single insulated power cable which increases the risk of premature failure. A power cable failure may result in the hoist structure becoming live when the hoist is connected to the mains supply for battery charging and could expose the caregiver or patient to a risk of electrical shock.

The following hoists are potentially be affected by this issue:

- Cricket – 3
- Cypress – 2
- Ergolift
- Ergolift 600
- ErgoStand
- Explorer
- Explorer 600
- Graduate
- Junior
- Medilifter-IV
- Mezzo
- Ministand
- ML-4
- Primo
- Sherpa
- SSL-2
- Standup
- Trekker
- Xtreme

The manufacturer issued a field safety notice in February 2010 to advise

The manufacturer issued a field safety notice in February 2010 to advise users how to identify the affected cables. The affected cables are to be replaced with double insulated cables.

Part 5. Action to be taken

a) Action to be taken:

The manufacturer and the distributors of this device in Ireland have been unsuccessful in their attempts to locate all hoists affected by this field safety corrective action (FSCA).

The IMB advises that users:

- Follow the manufacturer's recommendations as outlined in the attached field safety notice.
- Identify the affected hoists in your facility and contact the manufacturer to arrange for a power cable replacement.
- Remove any affected devices from service pending installation of the new power cable.

Part 6. Enquiries

a) All enquiries should be made to:

Enquiries to the manufacturer / European authorised representative should be addressed to:

Mr. Paul Lovell

Group Regulatory Approvals Manager

ArjoHuntleigh

310-312 Dallow Road

Luton Bedfordshire

LU1 1TD

United Kingdom

Tel: +44 (0)1582 745891

Email: paul.lovell@huntleigh-technology.com

All adverse incidents relating to a medical device should be reported to the:

Irish Medicines Board

Kevin O'Malley House

Earlsfort Centre

Earlsfort Terrace

Dublin 2

Telephone: +353-1-6764971

Fax: +353-1-6344033

E-mail: vigilance@imb.ie

Website: www.imb.ie

[Please Click here to download a PDF Version of the Safety](#)

Website: www.imb.ie

[Please Click here to download a PDF Version of the Safety Notice](#)

[Please Click here to donwload Field Safety Notice](#)