

Advisory Notice

Reference Number	BES130417/1	Date of Issue	13.04.17
Device	Stealth Ultra Sub-Occipital Head Pad – Small & Medium	Range of Devices	610 600

<input type="checkbox"/> Immediate Action	<input checked="" type="checkbox"/> Action
<input type="checkbox"/> Update	<input type="checkbox"/> Information

Problem

The small & medium versions of the Ultra Sub-Occipital Head Pad (610 & 600) supplied within the last 12 months may have a fault with the welding on the internal metal work. The weld is not strong enough to take the minimum pull requirements of 75lbs.

Action by Whom

BES to make contact with all customers who have purchased these head pads since March 2016. BES have checked all current stocks to ensure that no further at-risk head pads are despatched.

Stealth Products Inc. have confirmed that they have now changed the weld process that are being used in the manufacturing process to ensure that they are secure.

Action Required

Replacement head pads to be issued and fitted.

Distributed to

Customers who have purchased 610 and 600 Head Pads since March 2016.

Contact

Nikki ter Haar – Quality Assurance Manager
Tel: 01179 666 761 Email: nth@bescorporate.net