



IRISH MEDICINES BOARD  
FIELD SAFETY NOTICE MONTHLY SUMMARY SHEET- NOVEMBER 2010

Product	Manufacturer	Type	Link to FSN
VLP Compression Plate 7 Hole 56 mm, product code 72824014S	Smith&Nephew	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Sonopet Ultrasonic Aspirator Console	Stryker	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
seca 955 and seca 959 chair scales	Seca	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Neotrode, Neotrode II, Softrace Neonatal, Softrace Pediatric and Softrace Limb Band ECG Electrodes	ConMed Corporation	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Feeding Tube with Luer Lock	Unomedical	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
E.CAM patient handling system	Siemens	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
Contrak	Merck Serono / Corpak	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
i-STAT Celite ACT Cartridges & i-STAT Kaolin cartridges	Abbott Point of Care	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Armstrong Medical Mapleson C, Ayre's T piece and UltraBain breathing circuits containing an Ultra APL valve	Armstrong Medical	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
LINEAGE® Liners, Rim-Lock Liners	Wright Medical Technology	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Trinity Biotech	G-6-PDH Control, Normal	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
KlinoPORT	Trumpf	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Merit VacLok/Medallion Syringe	Merit Medical Systems Inc.	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
AIDA COMPACT II (20040601-U)	Karl Storz Endoscopy	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
SPECTRA XY Link Ceiling Track Hoist Model HS200XY, H162 & H160 and Parts	Southern Care Systems Ltd.	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>

Product	Manufacturer	Type	Link to FSN
CCA application running on the Extended Brilliance Workspace (EBW) and Brilliance Workspace Portal	Philips	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
Allura Xper Systems and Allura Integris Systems, Multi Diagnost Eleva and Omni Diagnost Eleva Systems	Philips	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Micrus Endovascular Microcoil System	Micrus	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Double Adjustable Crutch (Forearm Crutch) - Umoc22839	Ultimate Healthcare	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
UltraSteriSet	Gambro	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Tinaquant D-Dimer Gen II	Roche Diagnostics	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Cell-Dyn Emerald	Abbott Laboratories	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Intellivue Information Center	Philips	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
Microseal Master Cones	SybronEndo	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
BD 5ml Plastipak Syringe Luer-Lok™ Tip	BD Medical	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Herz-Lungen-Maschine / heart-lung-machine, HLM (Model HL20)	Maquet Cardiopulmonary AG	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Interpulse System	Stryker	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Axiom Luminos dRF with compression device	Siemens	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
Accessory Babix holder at VS wallstands of BuckyDiagnost, EasyDiagnost and DigitalDiagnost systems	Philips	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
OttoBock Discovery Wheelbases supplied with Leckey Mygo Seating Systems	James Leckey Design Limited	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Beamview TI Portal Imaging system	Siemens	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>

Product	Manufacturer	Type	Link to FSN
Grab Handle	Delta Sport, distributed by Lidl	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Leica Biosystems	Bond Polymer Refine Detection DS9800	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Naturecare CD2000 and Naturecare CD2020	Champion Photochemistry SDN BHD	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Dimension Vista Gentamicin (GENT) Flex reagent cartridge	Siemens Healthcare Diagnostics	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Bath Corner Chair	Smirthwaite	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Behring Coagulation System	Siemens Healthcare Diagnostics	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Various single shot epidural kits, Venous access kits and arterial line kits	Teleflex Medical	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
CO2 Insufflator Flow	Ulrich Medical	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
Sarns™ Ultrasonic Air Sensor – Air Sensor Cable	Terumo UK Ltd	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Flow-I Anaesthesia Gas Scavenging System	Maquet Critical Care AB	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Matrix2™ Detachable Coil	Boston Scientific	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Perossal® 1X6 Und 2X6 - 03-01031 And 03-01032	AAP Biomaterials Gmbh	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
Action 3NG Wheelchair	Invacare	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Focal	Elekta CMS	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
TPSA Flex reagent cartridges, FPSA Flex reagent cartridges and PSA Calibrator	Siemens Healthcare Diagnostics	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Carescape Monitor B650	GE Healthcare	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
Syngo® TrueD VC22B on Syngo® Studio, Advanced V3x	Siemens Medical Solutions USA Inc.	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>

Product	Manufacturer	Type	Link to FSN
Shimadzu UD150 B,V,L -40	MIS Medical Imaging Systems	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
GE Centricity™ PACS-IW	GE Healthcare	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
IntelliVue Clinical Information Portfolio Release D.00 to D.03	Philips	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
Microspeed Uni-Arthro Control Units and Motors	Aesculap AG	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
Synchron LX and UniCel® DxC Clinical Systems Operating Software	Beckman Coulter	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Austin Moore Hip Prosthesis	B Braun	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Acetaminophen	Roche Diagnostics	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Pegasus and Megabus Stretcher Trolleys	Ferno	Advice has been provided by the manufacturer regarding a device modification	<a href="#">Manufacturer's FSN</a>
NanoCross™ .014 OTW Dilatation Catheter	ev3 Inc.	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Straight Rasp Handle	Stryker	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Zimmer® Natural Nail™ System Cephalomedullary Lag Screw Inserters	Zimmer Inc.	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Access Total βhCG	Beckman Coulter	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Filter for dialysate purification EF-02 D	Nikkiso	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Whole Blood Controls for Use with Hemochron Koalin and Celite HRT Test Tubes; RQHRT	International Technidyne Corporation (ITC)	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Accu-Chek Inform meter	Roche Diagnostics	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
GENius™ Multi-Channel RF Generator	Medtronic	Advice has been provided by the manufacturer regarding changes/updates made to instructions for use	<a href="#">Manufacturer's FSN</a>
MOUNTAINEER® Screw Caddy	DePuy	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
HiRes 90K cochlear implant	Advanced Bionics	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>

Product	Manufacturer	Type	Link to FSN
Oxoid Legionella BCYE Growth Supplement	ThermoFisher Scientific	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Valved One-Step Centesis Drainage Catheter	Merit Medical Systems Inc.	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Xcelerate Ceramic 4:1 Cutting Blocks	Stryker Orthopaedics	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
UniCel® DxC 600 / 600 PRO / 600i / 800 / 800 PRO / 880i / 860i / 680i / 660i	Beckman Coulter	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
ConchaTherm Neptune Heated Humidifiers with Heated Wire Breathing Circuits	Teleflex Medical	Advice has been provided by the manufacturer regarding a software upgrade	<a href="#">Manufacturer's FSN</a>
Dycal Calcium Hydroxide Liner	Dentsply	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Nursing Bed, model Scanbed 750	Invacare	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>
Stryker® Orthopaedics Passport® A.R. Knee Instrumentation Distal Guide Stand & Scorpio Punch Thru Tibial Baseplates	Stryker Orthopaedics	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
Symbiq Administration Sets	Hospira	Advice has been provided by the manufacturer regarding a device removal	<a href="#">Manufacturer's FSN</a>
CARESCAPE Monitor B850	GE Healthcare	Advice has been provided by the manufacturer regarding the use of the device	<a href="#">Manufacturer's FSN</a>