

Field Safety Notice Summary Sheet

Outstanding Field Safety Corrective Actions

Field safety notices included in this summary sheet since the last issuance of this document are highlighted in grey

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|---------------------|---|----------------|------------------------------------|
| V26786 | ReoPro Filter kit | Eli Lilly | Advice has been provided regarding the use of the device | February 2016 | Manufacturer's FSN |
| V24665 | Dolomite rollators: Futura, Melody, Legacy, Maxi+, Alpha, Symphony, Jazz 520 and Jazz 600 | Invacare | Advice has been provided regarding changes/updates made to instructions for use | October 2015 | Manufacturer's FSN |
| V25335 | JCM Compact Base | JCM | Advice has been provided regarding a device modification | August 2015 | Manufacturer's FSN |
| V27708 | Immunoassay Control, Immunoassay Premium Plus Control | Randox | Advice has been provided regarding a device modification | August 2015 | Manufacturer's FSN |
| V24017 | Accu-Chek Spirit Combo insulin pump / Accu-Chek Spirit insulin pump | Roche Diabetes Care | Advice regarding the use of the device | May 2015 | Manufacturer's FSN |
| V23462 | Invacare® Leo®, Invacare® Orion® & Invacare® Comet® Scooters | Invacare | Advice regarding the use of the device | March 2015 | Manufacturer's FSN |
| V23640 | Keeler Wall Plug Power Supply | Keeler Ltd | Advice regarding the use of the device | March 2015 | Manufacturer's FSN |
| V23309 | CADD™ Medication Cassette Reservoir, 50ml | Smiths Medical | Advice has been provided regarding a device removal | February 2015 | Manufacturer's FSN |
| V20596 | Merck Serono pH Indicator Strips 0-6.0, Merck Serono pH Indicator Strips 2.0-9.0 | Merck Serono | Advice regarding changes/updates made to instructions for use | Nov 2014 | Manufacturers FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|--------------------------|---|----------------|------------------------------------|
| V22468 | Medtronic MiniMed Enlite™ Glucose Sensor | Medtronic | Advice has been provided regarding a product removal | November 2014 | Manufacturer's FSN |
| V22478 | MiniMed Silhouette™ and Sure-TTM infusion sets | Medtronic | Advice has been provided regarding the use of the device | November 2014 | Manufacturer's FSN |
| V22601 | Perfect O2, Perfect O2V, Platinum S, Platinum 9 | Invacare | Advice has been provided regarding a device modification | November 2014 | Manufacturers FSN |
| V20596 | Merck Serono pH Indicator Strips 0-6.0, Merck Serono pH Indicator Strips 2.0-9.0 | Merck Serono | Advice regarding changes/updates made to instructions for use | May 2014 | Manufacturers FSN |
| V20868 | Accu-Chek Mobile System | Roche Diabetes Care | Advice regarding the use of the device | May 2014 | Manufacturer's FSN |
| V20981 | Drive Walking Frames (10284-30 and 10284W-30) | Drive Medical | Advice regarding the use of the device | May 2014 | Manufacturer's FSN |
| V20802 | DETEX X-Ray Detectable Swabs | Synergy Health | Advice has been provided regarding a device removal | May 2014 | Manufacturer's FSN |
| V20542 | A200 Power Wheelchair / Skippi & Skippi Plus Power Wheelchair | Ottobock Healthcare | Advice has been provided regarding a device modification | April 2014 | Manufacturer's FSN |
| V20491 | Oxoid Antimicrobial Susceptibility Testing (AST) Discs - Meropenem MEM10 | Thermofisher Scientific | Advice regarding the use of the device | April 2014 | Manufacturer's FSN |
| V19644 | Pegasus Alternating Mattresses X2 Capacitor, affecting Biwave, Cairwave, Trinova and Viaclin Pumps | ArjoHuntleigh | Advice has been provided regarding a device modification | March 2014 | Manufacturer's FSN |
| V20264 | Alaris® SmartSite® Needle-Free Valve | CareFusion International | Advice has been provided regarding a device removal | February 2014 | Manufacturer's FSN |
| V19783 | Comploglass F | Ivoclar Vivadent | Advice has been provided regarding a device removal | January 2014 | Manufacturer's FSN |
| V19737 | BD Plastipak™ 50mL Luer Lok Syringes | BD Medical | Advice regarding the use of the device | January 2014 | Manufacturer's FSN |
| V19736 | Kodak 2100 and Kodak 2200 Intraoral x-ray Systems | Carestream | Advice has been provided regarding a device modification | January 2014 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|---------------------------------|---|----------------|------------------------------------|
| V19091 | SynReam Medullary Reamer Head 8.5mm | DePuy Synthes | Advice has been provided regarding a device removal | December 2013 | Manufacturer's FSN |
| V19092 | Accu-Chek® Aviva Combo Handset | Roche | Advice regarding the use of the device | October 2013 | Manufacturer's FSN |
| V19001 | Liko® SlingBar™ 350, SlingBar™ 360, SlingBar™ Wide 670, and SideBar™ Standard | Liko / Hill-Rom | Advice has been provided regarding a device modification | October 2013 | Manufacturer's FSN |
| V19047 | Power Chair, model Q600, Q600XL, Q600 Sport, Q6 Edge, Q600 Sport HD | Pride Mobility Products Limited | Advice has been provided regarding changes/updates made to instructions for use | October 2013 | Manufacturer's FSN |
| V18007 | Patterson Walking Sticks – 404 model | Patterson Medical | Advice has been provided regarding a device removal | June 2013 | Manufacturer's FSN |
| V18008 | Patterson Walking Frames | Patterson Medical | Advice has been provided regarding a device removal | June 2013 | Manufacturer's FSN |
| V17822 | CoaguChek XS; CoaguChek XS Plus; CoaguChek XS Pro | Roche | Advice regarding the use of the device | May 2013 | Manufacturer's FSN |
| V17530 | Ormco BV Europe | Bracket Buccal Tubes | Advice has been provided regarding a device removal | April 2013 | Manufacturer's FSN |
| V17378 | Invacare REA Assist wheelchairs | Invacare | Advice has been provided regarding changes/updates made to instructions for use | March 2013 | Manufacturer's FSN |
| V16981 | ML 301 examination lamp with Ondal Acrobat® Swing spring arm | Gebruder Martin GmbH & Co. KG | Advice has been provided regarding a device removal | January 2013 | Manufacturer's FSN |
| V16448 | Freeway Hoists / Ta Xtra Hoists | Prism Medical UK | Advice has been provided regarding a device modification | November 2012 | Manufacturer's FSN |
| V16769 | Liko Ceiling Mounted Overhead Rail Systems | Hill-Rom Luleå | Advice has been provided regarding a device modification | November 2012 | Manufacturer's FSN |
| V16038 | PSX Proximate® Skin Staple Extractor | Ethicon Endo-Surgery | Advice has been provided regarding a device removal | October 2012 | Manufacturer's FSN |
| V16271 | REA Azalea Base | Invacare | Advice regarding the use of the device | October 2012 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|-----------------------|---|----------------|--|
| V15478 | OptimaXL, Sirius, XLED, Xenon Handles | Timesco | Advice has been provided regarding a device removal | August 2012 | Manufacturer's FSN |
| V15533 | Minivator Bath Bliss Reclining Bathlift 311 | Handicare Limited | Advice has been provided regarding a device modification | August 2012 | Manufacturer's FSN |
| V15066 | FreeSpan Traverse and FreeSpan UltraTwin Traverse Freestanding Lift Systems | Hill-Rom / Liko | Advice has been provided regarding changes/updates made to instructions for use | July 2012 | Manufacturer's FSN |
| V15355 | KleenSpec Disposable Vaginal Specula | Welch Allyn | Advice has been provided regarding the use of the device | July 2012 | Manufacturer's FSN |
| V15322 | Neonatal and paediatric endotracheal tube clamp/holders | EMS Medical | Advice has been provided regarding a device removal | July 2012 | MHRA Medical Device Alert |
| V15978 | Sabina and Capella Sit-to-Stand mobile lifts | Liko AB | Advice has been provided regarding a device modification | June 2012 | Manufacturer's FSN Manufacturer's FSN |
| V14956 | Harrier Range Wheelchairs | Invacare | Advice regarding the use of the device | May 2012 | Manufacturer's FSN |
| V14764 | Birdie & Flamingo Lifters | Invacare | Advice has been provided regarding a device modification | May 2012 | Manufacturer's FSN |
| V14969 | Zimma Walking Frame | Invacare | Advice has been provided regarding a device modification | May 2012 | Manufacturer's FSN |
| V14583 | Hera II Bathing and Toileting Chair | Ergolet | Advice has been provided regarding a device modification | April 2012 | Manufacturer's FSN |
| V14241 | Avant, Avant LW and Salsa Walkers | Etac Supply Center AB | Advice has been provided regarding a device modification | February 2012 | Manufacturer's FSN |
| V14306 | Freeway Mobile Hoists | Prism Medical UK | Advice has been provided regarding a device modification | February 2012 | Manufacturer's FSN |
| V13274 | Walker Etac ONO | Etac AB | Advice has been provided regarding a device modification | February 2012 | Manufacturer's FSN |
| V14609 | GH3/GH1 Trolley | Guldmann | Advice has been provided regarding a device modification | February 2012 | Manufacturer's FSN |
| V13699 | Vector TAS Modular Driver | Ormco Europe B.V. | Advice has been provided regarding changes/updates made to instructions for use | January 2012 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|--|---|----------------|---|
| V14154 | Syngo.Plaza | Siemens AG Healthcare Sector | Advice has been provided regarding a software upgrade | January 2012 | Manufacturer's FSN |
| V14151 | Syngo.Plaza | Siemens AG Healthcare Sector | Advice has been provided regarding a software upgrade | January 2012 | Manufacturer's FSN |
| V13634 | Sterimar Isotonic 100ml | Church & Dwight UK Limited | Advice has been provided regarding a device removal | December 2011 | Manufacturer's FSN |
| V13906 | NP150 Mattress | Hill Rom | Advice has been provided regarding changes/updates made to instructions for use | December 2011 | Manufacturer's FSN |
| V13456 | Level 1® D/DI-60HL Normothermic IV Administration Sets: D-60HL, DI-60HL | Smiths Medical | Advice has been provided regarding a device removal | November 2011 | Manufacturer's FSN |
| V13456 | HOTLINE® Disposable Administration Sets: L-70, L- 70NI, L-80, L-270 and L-370 | Smiths Medical | Advice has been provided regarding a device removal | November 2011 | Manufacturer's FSN |
| V13356 | Puma, Beatle, Alex and Ibis XP Power Wheelchairs | Handicare | Advice has been provided regarding a device modification | November 2011 | Manufacturer's FSN |
| V13343 | REA Assist Wheelchairs | Invacare | Advice regarding the use of the device | November 2011 | Manufacturer's Technical Bulletin |
| V10346 | X220, X221, X312 and X313 Bariatric Commodes | Cefndy Healthcare | Advice has been provided regarding a device modification | November 2011 | Manufacturer's FSN |
| V13303 | Abbott FreeGo enteral feeding pump | Abbott Laboratories Ireland Limited | Advice has been provided regarding a device modification | November 2011 | Manufacturer's FSN |
| V12925 | Drive Medical Nimbo Paediatric Walkers | Drive Medical | Advice has been provided regarding changes/updates made to instructions for use | September 2011 | Manufacturer's FSN |
| V12924 | Drive WA007 Rollators | Drive Medical | Advice has been provided regarding a device modification | August 2011 | Manufacturer's FSN |
| CP9967 | Explorer Loop 4 Wheeled Rollators | Murrays Medical Equipment Limited | Advice has been provided regarding a device removal | August 2011 | Manufacturer's Customer Letter |
| V13017 | Endres Riviera Bathlift | Drive Medical | Advice has been provided regarding changes/updates made to instructions for use | August 2011 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|-------------------------------------|---|----------------|------------------------------------|
| V12469 | Linnet Eleganza Standard & Deluxe Model Bedframes | Linnet | Advice has been provided regarding a device modification | July 2011 | Manufacturer's FSN |
| V12351 | Wispa Portable Hoist and Attachment Handle | Chiltern Invadex UK Limited | Advice has been provided regarding a device modification | July 2011 | Manufacturer's FSN |
| V12466 | Pressure Area Care Mattresses and Cushions | Talley Group | Advice has been provided regarding changes/updates made to instructions for use | July 2011 | Manufacturer's FSN |
| V9506 | CERAGEM-E Massage Bed | CERAGEM Co. Limited | Advice has been provided regarding changes/updates made to instructions for use | July 2011 | Manufacturer's FSN |
| V12465 | ArjoHuntleigh lifting poles with an adjustable strap and handle - ROLKO strap and handle | ArjoHuntleigh | Advice has been provided regarding a device removal | July 2011 | Manufacturer's FSN |
| V12399 | Marus brand LuxStar Dental Lights (Model OL1000) | Marus | Advice has been provided regarding a device modification | July 2011 | Manufacturer's FSN |
| V12134 | OXFORD Easytrack 2, 3 & 4 Post Systems | Joerns Healthcare | Advice has been provided regarding use of the device | June 2011 | Manufacturer's FSN |
| V12482 | Waverly Glen Transactive (TA) Hoists and Waverly Glen Transportable (TP) Hoists | Prism Medical UK | Advice has been provided regarding a device modification | June 2011 | Manufacturer's FSN |
| V12187 | Moving Solutions Slings | Nottingham Rehab Supplies | Advice has been provided regarding changes/updates made to instructions for use | June 2011 | Manufacturer's FSN |
| V8535 | Xcelerate Ceramic 4:1 Cutting Blocks | Stryker Orthopaedics | Advice has been provided regarding a device removal | June 2011 | Manufacturer's FSN |
| V12061 | PELIspec vaginal speculums | Pelican Feminine Healthcare Limited | Advice has been provided regarding a device removal | May 2011 | Manufacturer's FSN |
| V11933 | LogiCal®, NovaTrans®, and TranStar® Invasive Pressure Monitoring Systems | Smiths Medical | Advice has been provided regarding a device removal | May 2011 | Manufacturer's FSN |
| V12142 | Scanbed 400 Nursing Bed | Invacare | Advice has been provided regarding changes/updates made to instructions for use | May 2011 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|---------------------------|---|----------------|------------------------------------|
| V11405 | Romachair Model 4730 / 4740 | Roma Medical | Advice has been provided regarding a device modification | March 2011 | Manufacturer's FSN |
| V11437 | Applix Smart and Applix Vision Nutrition Enteral Feeding Pumps | Fresenius Kabi Limited | Advice has been provided regarding a device modification | March 2011 | Manufacturer's FSN |
| V11227 | Quickie Neon Swing Away Wheelchair | Sunrise Medical | Advice has been provided regarding a device modification | February 2011 | Manufacturer's FSN |
| V11133 | Mikro 120 | Andreas Hettich GmbH & Co | Advice has been provided regarding a device modification | January 2011 | Manufacturer's FSN |
| V8682 | Action 3 and Action 4 Manual Wheelchairs | Invacare | Advice has been provided regarding changes/updates made to instructions for use | January 2011 | Manufacturer's FSN |
| V11096 | Mobility Powerchairs Control System Changes | Invacare | Advice has been provided regarding the use of the device | January 2011 | Manufacturer's FSN |
| V11339 | Samba Chair (Product Codes 8801, 8802, 8803, 8804, 8810) | G&S Smirthwaite Limited | Advice has been provided regarding a device modification | January 2011 | Manufacturer's FSN |
| V10897 | Typhoon II Power Wheelchair with Stability Lock | Invacare | Advice has been provided regarding a device modification | December 2010 | Manufacturer's FSN |
| V10177 | Seca 955 and Seca 959 chair scales | Seca | Advice has been provided regarding a device modification | October 2010 | Manufacturer's FSN |
| V10465 | Peristeen Anal Irrigation System | Coloplast | Advice has been provided regarding changes/updates made to instructions for use | October 2010 | Manufacturer's FSN |
| V10419 | Relactagel | Kora Healthcare | Advice has been provided regarding a device removal | October 2010 | Manufacturer's FSN |
| V10480 | Static Mattresses | Park House Healthcare | Advice has been provided regarding changes/updates made to instructions for use | October 2010 | Manufacturer's FSN |
| V10222 | All Freeway Shower Chairs with integral drop down armrests | Prism Medical UK | Advice has been provided regarding a device modification | September 2010 | Manufacturer's FSN |
| V10525 | SOPIRA Carpule Needles | Heraeus | Advice has been provided regarding a device removal | September 2010 | Manufacturer's FSN |
| V10188 | Oxford Weigh-scale item OP97000 | Joerns Healthcare | Advice has been provided regarding the use of the device | August 2010 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|-----------------------------|---|----------------|------------------------------------|
| V10178 | Pride Riser Recliner | Pride Mobility Products | Advice has been provided regarding changes/updates made to instructions for use | August 2010 | Manufacturer's FSN |
| V10587 | Oxford Midi 150A Hoists | Joerns Healthcare | Advice has been provided regarding the use of the device | July 2010 | Manufacturer's FSN |
| V9998 | Comfort 4 Therapy Chair | Digitherm | Advice has been provided regarding a device modification | July 2010 | Manufacturer's FSN |
| V9585 | SleepStyle™ Series CPAP Power Cord Product Replacement | Fisher & Paykel Healthcare | Advice has been provided regarding a device modification | July 2010 | Manufacturer's FSN |
| V1408 | ArjoHuntleigh alternating pressure therapy systems | ArjoHuntleigh | Advice has been provided regarding a device modification | June 2010 | Manufacturer's FSN |
| V9656 | LikePak 20 and Lifepak 20e | Physio Control | Advice has been provided regarding a device modification | June 2010 | Manufacturer's FSN |
| V9819 | Trachidress | Kapitex Healthcare Limited | Advice has been provided regarding a device removal | March 2010 | Manufacturer's FSN |
| V8911 | BHM Medical Inc. Hoists | BHM Medical Inc. | Advice has been provided regarding a device modification | February 2010 | Manufacturer's FSN |
| V8947 | Dycal Radiopaque Calcium Hydroxide Composition Cavity Base/Liner | DENTSPLY Caulk | Advice has been provided regarding a device removal | February 2010 | Manufacturer's FSN |
| V9006 | Ondal Acrobat 2000 Sprung Arm used to carry HELION and XENION surgical lights and monitors | TRUMPF Medizin Systeme GmbH | Advice has been provided regarding a device modification | February 2010 | Manufacturer's FSN |
| V11627 | Harmony LA, LC 500 and LA 700 Surgical Lighting and Media System | Steris | Advice has been provided regarding a device modification | February 2010 | Manufacturer's FSN |
| V7581 | New Bug Push Chair | Ormesa | Advice has been provided regarding changes/updates made to instructions for use | February 2010 | Distributor's FSN |
| V8642 | Hill-Rom beds with Monkey Pole (Lifting Pole) | Rolko Kohlgrüber GmbH | Advice has been provided regarding a device removal | January 2010 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|---|---|----------------|---|
| V8682 | Action 3 and Action 4 Manual Wheelchairs | Invacare | Advice has been provided regarding changes/updates made to instructions for use | January 2010 | MHRA Medical Device Alert |
| V8917 | Appollo Special Needs Bathing Products, models: Elegance, Excalibur and Apollo | Reva Industries Limited | Advice has been provided regarding a device modification | December 2009 | Manufacturer's FSN |
| V7832 | Thermo contour mattress | Barrington Healthcare International Limited | Advice has been provided regarding changes/updates made to instructions for use | December 2009 | Manufacturer's FSN |
| V8352 | Oxford Hoists | Joerns Healthcare | Advice has been provided regarding the use of the device | November 2009 | Manufacturer's FSN |
| V8391 | Oxford Slings | Joerns Healthcare | Advice has been provided regarding changes/updates made to instructions for use | November 2009 | Manufacturer's FSN |
| V7962 | Ondal Acrobat 2000 spring arms used in ML, marLUX and marLED operating light suspensions | Gebrüder Martin GmbH & Co. KG | Advice has been provided regarding a device modification | August 2009 | Manufacturer's FSN |
| V8038 | Birdie Patient Lifter | Invacare | Advice has been provided regarding a device modification | August 2009 | Manufacturer's FSN |
| V9970 | Permobil Wheelchairs | Permobil | Advice has been provided regarding changes/updates made to instructions for use | July 2009 | Manufacturer's FSN |
| V7741 | AquaJoy Premier Plus and Junior Plus Bathlifts | AquaJoy Bathlifts Limited | Advice has been provided regarding changes/updates made to instructions for use | July 2009 | Manufacturer's FSN |
| V7731 | Rea Azalea Base Wheelchair | Invacare | Advice has been provided regarding a device modification | July 2009 | Manufacturer's FSN |
| V8196 | Rea Assist Backrest Bow | Invacare | Advice has been provided regarding a device modification | July 2009 | Manufacturer's FSN |
| V7845 | Escape Lite Wheelchairs | Patterson Medical, formerly Days Healthcare | Advice has been provided regarding the use of the device | July 2009 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|------------------------|---|----------------|---|
| V7835 | AC2000 Spring Arm | Ondal Industrietechnik | Advice has been provided regarding a device modification | June 2009 | Manufacturer's FSN |
| V11227 | Icelock® Expulsion Valve 551 | Össur | Advice has been provided regarding a device removal | June 2009 | Manufacturer's FSN |
| V8301 | Passive Patient Lifts and Ceiling Lifts | ArjoHuntleigh | Advice has been provided regarding a device modification | June 2009 | Manufacturer's FSN |
| V7431 | T34 Sytinger Driver | CME McKinley | Advice has been provided regarding a device modification | May 2009 | Manufacturer's FSN |
| V7404 | Harrier Range (Plus, HD & XHD) wheelchairs | Invacare | Advice has been provided regarding changes/updates made to instructions for use | May 2009 | Manufacturer's FSN |
| V7581 | New Bug Push Chair | Ormesa | Advice has been provided regarding changes/updates made to instructions for use | May 2009 | Manufacturers Revised IFU |
| V7078 | Bed Side Rails - 1025 range, 1031 range, SP 1027 range | Corona Medical | Advice has been provided regarding the use of the device | March 2009 | Manufacturer's FSN |
| V6938 | All models of Jazzy, Quantum and LX battery powered wheelchairs | Pride Mobility Limited | Advice has been provided regarding changes/updates made to instructions for use | February 2009 | MHRA Medical Device Alert |
| V2774 | Flamingo hoist | Invacare | Advice has been provided regarding a device modification | February 2009 | Manufacturer's FSN |
| V6918 | Carina Home | Drager Medical | Advice has been provided regarding a device modification | January 2009 | Manufacturer's FSN |
| V6848 | Aluminium Walking Frames | Days Healthcare | Advice has been provided regarding a device modification | January 2009 | Manufacturer's FSN |
| V7143 | Posture Belt for use with Mobile Advance Seat, Contoured Advance Set, Squiggles Advance Seat and Squiggles Early Sitting System | Leckey | Advice has been provided regarding a device removal | January 2009 | Manufacturer's FSN |
| V7041 | Lifting Table Diagnostic 1171 | WaveLight AG | Advice has been provided regarding a device modification | January 2009 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|--------------------------------|---|----------------|------------------------------------|
| V6773 | Alaris PK Syringe Pump | Cardinal Health | Advice has been provided regarding the use of the device | January 2009 | Manufacturer's FSN |
| V7228 | Frimley folding stool model AA1550 | Homecraft Roylan Limited | Advice has been provided regarding a device modification | January 2009 | Manufacturer's FSN |
| V6996 | Action® 2000 manual wheelchair | Invacare | Advice has been provided regarding a device modification | January 2009 | Manufacturer's FSN |
| V3665 | Action 3 Wheelchairs fitted with ratchet reclining backrest | Invacare | Advice has been provided regarding changes/updates made to instructions for use | December 2008 | Manufacturer's FSN |
| V6770 | Liko Mobile Patient Lifts: Uno, Viking S, Viking XS, LikoLight | Liko AB | Advice has been provided regarding a device modification | December 2008 | Manufacturer's FSN |
| V2391 | Strider Maxi & Strider Midi 4 Plus Scooters | Days Healthcare | Advice has been provided regarding a device modification | November 2008 | Manufacturer's FSN |
| V6483 | Flocare® Infinity Enteral Feeding Pump | Nutricia | Advice has been provided regarding a software upgrade | November 2008 | Manufacturer's FSN |
| V4050 | Transportation of Storm 3 Range (including Storm 3 TT), Typhoon 1 & 2 power wheelchairs | Invacare | Advice has been provided regarding changes/updates made to instructions for use | November 2008 | Manufacturer's FSN |
| V6810 | Avantgarde Back Tube | Otto Bock Healthcare | Advice has been provided regarding a device modification | September 2008 | Manufacturer's FSN |
| V6574 | Battery charger for Mermaid and Historic Oxford hoists | Joerns Healthcare | Advice has been provided regarding use of the device | September 2008 | Manufacturer's FSN |
| V6139 | Siroclave | Sirona | Advice has been provided regarding a device modification | August 2008 | Manufacturer's FSN |
| V6125 | Baby Sleepsafe Monitor, model AE 010 M | Axminister Electronics Limited | Advice has been provided regarding a device modification | August 2008 | Manufacturer's FSN |
| V6188 | Reliant lifter 100 / 150 / 200 / 250 | Invacare | Advice has been provided regarding changes/updates made to instructions for use | August 2008 | Manufacturer's FSN |
| V6655 | Sunrise Medical Manual and Powered Wheelchairs | Sunrise Medical | Advice has been provided regarding changes/updates made to instructions for use | July 2008 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|----------------------|---|----------------|------------------------------------|
| V6014 | LIFEPAK CR Plus and/or LIFEPAK EXPRESS Defibrillators | Medtronic Limited | Advice has been provided regarding a device modification | July 2008 | Manufacturer's FSN |
| V6368 | 2" and 4" Savannah raised toilet seats | Homecraft Roylan | Advice has been provided regarding a device modification | July 2008 | Manufacturer's FSN |
| V4180 | Walking frames | Trulife | Advice has been provided regarding a device modification | June 2008 | Manufacturer's FSN |
| V5837 | Liko Universal SlingBar | Liko AB | Advice has been provided regarding a device modification | June 2008 | Manufacturer's FSN |
| V6016 | Medi-Tec Classic Hoist | Aidservice Limited | Advice has been provided regarding a device modification | June 2008 | Manufacturer's FSN |
| V6178 | Kaye Posture Control Walker | Quest 88 | Advice has been provided regarding a device modification | May 2008 | Manufacturer's FSN |
| V6791 | Maxi Sky 600 – Infrared (IR) System | Arjo Technical | Advice has been provided regarding a device modification | May 2008 | Manufacturer's FSN |
| V5907 | Power Module (part of RiwoMobile) | Richard Wolf GmbH | Advice has been provided regarding a device removal | May 2008 | Manufacturer's FSN |
| V4152 | Huntleigh birthing bed mattresses used with Birthright Bed models 35000 (manual) and 170000 (electric) versions and Hoskins Birthcare bed models L05 and L10 | Huntleigh Healthcare | Advice has been provided regarding changes/updates made to instructions for use | April 2008 | Manufacturer's FSN |
| V4069 | AKW 2000 series shower seat | ADW MediCare | Advice has been provided regarding a device modification | March 2008 | Manufacturer's FSN |
| V4025 | Ambulift / Ambulift Power and Ambulift Classic Lifters | Arjo | Advice has been provided regarding a device modification | March 2008 | Manufacturer's FSN |
| V4024 | NovaTrans, Transtar Invasive Pressure Monitoring Kits with Trigger Flush Device | Smiths Medical | Advice has been provided regarding changes/updates made to instructions for use | February 2008 | Manufacturer's FSN |
| V5905 | Intelect | Chattanooga Group | Advice has been provided regarding a software upgrade | January 2008 | Manufacturer's FSN |
| V3912 | Birthright beds and Hoskins Birthcare beds | Huntleigh Healthcare | Advice has been provided regarding a device modification | January 2008 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|---|-------------------------------------|---|----------------|------------------------------------|
| V3855 | Stryker stretchers | Stryker | Advice has been provided regarding a device modification | January 2008 | Manufacturer's FSN |
| V3866 | Applix Smart Enteral Feeding Pumps | Fresenius Kabi | Advice has been provided regarding the use of the device | January 2008 | Manufacturer's FSN |
| V4015 | InChair Sling | Care & Independence Systems Limited | Advice has been provided regarding changes/updates made to instructions for use | January 2008 | Manufacturer's FSN |
| V3946 | Module DPS | Fresenius Kabi | Advice has been provided regarding a device modification | January 2008 | Manufacturer's FSN |
| V3946 | Module DPS | Fresenius Kabi | Advice has been provided regarding a device modification | January 2008 | Manufacturer's FSN |
| V3656 | Active Pump | Invacare | Advice has been provided regarding a device modification | December 2007 | Manufacturer's FSN |
| V3852 | Phase Cells | Park House Healthcare | Advice has been provided regarding a device modification | December 2007 | Manufacturer's FSN |
| V3665 | Action 3 Wheelchairs fitted with ratchet reclining backrest | Invacare | Advice has been provided regarding changes/updates made to instructions for use | December 2007 | Manufacturer's FSN |
| V3798 | Konstant Battery Charger 24V 6A | Lomax Mobility & Sunrise Medical | Advice has been provided regarding a device modification | November 2007 | Manufacturer's FSN |
| V3652 | Kimba Spring Paediatric Buggy | Ottobock Healthcare | Advice has been provided regarding a device modification | October 2007 | Manufacturer's FSN |
| V3665 | Action 3 Wheelchairs fitted with ratchet reclining backrest | Invacare | Advice has been provided regarding a device modification | October 2007 | Manufacturer's FSN |
| V3693 | Frazier and Poole Suction Instruments | ConMed Corporation | Advice has been provided regarding a device removal | September 2007 | Manufacturer's FSN |
| V3652 | Kimba Spring Range | Otto Bock Healthcare | Advice has been provided regarding a device modification | July 2007 | Manufacturer's FSN |
| V3348 | Contoura 880 beds | Huntleigh Healthcare | Advice has been provided regarding a device modification | May 2007 | Manufacturer's FSN |

| Case ID* | Product | Manufacturer | Type | Date Initiated | Link to FSN |
|----------|--|-------------------------|---|----------------|---|
| V3262 | Getinge models 8666, 8668, 46-2, 46-4, 46-5 Washer Disinfectors and S-607, S-608, S-617, S-618 and SP1000 Flusher Disinfectors | Getinge Disinfection AB | Advice has been provided regarding a device modification | April 2007 | Manufacturer's FSN |
| V3157 | LIFEPAK CR Plus and/or LIFEPAK EXPRESS Defibrillators | Medtronic Limited | Advice has been provided regarding a device modification | March 2007 | Manufacturer's FSN |
| V2961 | Kjaerulff Mini Lift Stand Aids | Kjaerulff A/S | Advice has been provided regarding a device modification | December 2006 | Manufacturer's FSN |
| V3138 | Spectra Plus powered wheelchair | Invacare | Advice has been provided regarding changes/updates made to instructions for use | December 2006 | Manufacturer's FSN |
| V2907 | REMstar Heated Humidifier | Philips Respironics | Advice has been provided regarding a device removal | October 2006 | Manufacturer's FSN |
| V2754 | Jay® J2 wheelchair backs | Sunrise Medical | Advice has been provided regarding changes/updates made to instructions for use | September 2006 | MHRA Medical Device Alert |
| V2349 | Rea Assist Armrests | Invacare | Advice has been provided regarding a device modification | April 2006 | Manufacturer's FSN |
| V2357 | Total Knees, models 1100, 1900, 2000 & 2100 | Össur | Advice has been provided regarding a device removal | March 2006 | Manufacturer's FSN |

** Based on feedback received, the HPRA has also included on this Field Safety Notice Summary Sheet a 'Case ID' for each listing. This is the HPRA's unique identifier for the individual FSN, and may be used by healthcare establishments in their systems as appropriate.*