

Notice Information: - Recall 20 August 2013

Part 1. Product Information

GlucoMen LX Sensor blood glucose test strips 50 count (product code 38877), used with the GlucoMen LX and GlucoMen LX PLUS meter

b) Product Name/Type: GlucoMen LX Sensor blood glucose test strips 50 count (product code 38877), used with the GlucoMen LX and GlucoMen LX PLUS meter

c) Reference: SN2013(09)

d) Manufacturer/Supplier: A. Menarini Diagnostics S.r.l. (Italy)

Part 2. Target Audience

a) Target Audience:

All Hospital staff

All Nursing Home staff

Risk Managers

Nursing Managers

Hospital Pharmacists

Diabetic Clinics/ outpatients

Diabetic nurse specialists

Diabetic departments

Endocrinology units

Endocrinology Consultants

Paediatric wards

Laboratory Managers

Chief Medical Scientists

Purchasing / Procurement / Material Managers

Pharmacists supplying these devices

General Practitioners

Healthcare professionals who use these devices

Healthcare professionals managing patients who use these devices

Carers

General public

Part 3. Problem/Issue

a) Problem/Issue:

The Irish Medicines Board (IMB) has been notified that certain lots of GlucoMen LX Sensor blood glucose test strips have been subject to a manufacturing fault and may give erroneously high blood glucose results, potentially leading to inappropriate insulin administration.

Part 4. Background Information

a) Background Information:

A. Menarini Diagnostics (UK) and the distributor Medicon Ireland have advised that blood glucose test strips from affected lot number 3212214249 (expiry date 2014-08-31) were supplied to the Irish market. Based on stock distribution patterns, both A. Menarini Diagnostics (UK) and Medicon Ireland believe that is unlikely that strips from this lot remain in circulation. Furthermore, A. Menarini Diagnostics has indicated that only a limited number of strips from the lot are affected by this issue.

A. Menarini Diagnostics (UK) and Medicon Ireland have confirmed that the above lot number is the only affected lot which they supplied to the Irish market; other affected lots (3212145249, 3212278249, 3212219249 and 3212251249) have been distributed in other European countries.

Part 5. Action to be taken

a)	Action to be taken:	Advice for End Users / Patients:
		Identify, discontinue use and quarantine devices from the affected lot.
		2. Return any devices from the affected lot to your pharmacy or distributor. Alternatively, contact A. Menarini Diagnostics (UK) or Medicon Ireland to arrange for return of any devices from the affected lot.
		3. Ensure that you can continue to appropriately monitor your blood glucose via test strips from a different lot number or by other means. This should be done in consultation with your healthcare professional.
		Advice for Healthcare Professionals / Pharmacists / Distributors :
		Identify, discontinue distribution and quarantine devices from the affected lot.
		2. Return any devices from the affected lot to your distributor. Alternatively, contact A. Menarini Diagnostics (UK) or Medicon Ireland to arrange for return of any devices from the affected lot.
		3. Please also pass this notice on to any end user or organisation where the potentially affected devices have been transferred or who are using the GlucoMen LX and GlucoMen LX PLUS meters.
		4. Ensure that the appropriate personnel and end users are made

aware of this notice.

5. Ensure that end users who return blood glucose test strips from the affected lots can continue to appropriately monitor their blood glucose.

Part 6. Enquiries

a) All enquiries should be made to:

ENQUIRIES:

All adverse incidents relating to a medical device should be reported to the:

Irish Medicines Board

Kevin O'Malley House

Earlsfort Centre

Earlsfort Terrace

Dublin 2

Telephone: +353-1-6764971

Fax: +353-1-6344033

E-mail: vigilance@imb.ie

Website: www.imb.ie

Enquiries to the distributor should be addressed to:

Mr. Jim McGrory

Medicon Ireland Ltd.

1a/1b Meridian Estate

Carnbane Business Park

Newry

Co. Down

BT356QH

Northern Ireland

Telephone: +44 2830 835 500

Fax: + 44 2830 835 544

Telephone: +44 2830 835 500

Fax: + 44 2830 835 544

E-mail: jimmcg@mediconire.com

Enquiries to the manufacturer should be addressed (via their UK affiliate) to:

Mr. Tony Jones

A. Menarini Diagnostics Ltd. (UK)

405 Wharfedale Road

Winnersh-Wokingham

RG41 5RA

Berkshire

United Kingdom

Telephone: +44 1189 444 100 or (+44 800 243 667)

Fax: +44 1189 444 123

E-mail: tony.jones@menarinidiag.co.uk

Please click here to view a PDF version of this Safety Notice