



# marus

---

## **Urgent Field Safety Notice**

**Marus Ref: 28 July-11**

*Marus brand LuxStar dental lights*

---

28 July 2011

Dear Customer:

### **Details on affected devices:**

This Field Safety Notice is applicable to the Marus brand LuxStar dental lights (model OL1000) with the following serial numbers: 4714B, 165569B, 12657B & 150179B

### **Description of the problem:**

Marus would like to inform you of a field corrective action regarding the Marus brand LuxStar dental lights to improve the overall safety of the device. The lens heat (bulb) shield (birdcage) on the Marus LuxStar dental lights, model OL1000, may potentially fall off the dental light if not properly installed after replacing the light bulb or if not properly maintained. This improper installation or maintenance could result in potential injury to either the patient or the clinician.

### **Advice on action to be taken by the user:**

Our self-install kit, part number 30792, has been developed to contain the required instructions and tools to allow easy installation by the staff within your office.

### **Contact reference person:**

Bonnie Dundas  
Quality Assurance and Regulatory Affairs Manager,  
Marus  
705 S. Springbrook Rd., Building C  
Newberg, OR 97132 U.S.A.  
Phone Number: 011-503-537-3602  
Fax Number: 011-503-537-3617  
E-mail: [bonnie.dundas@marus.com](mailto:bonnie.dundas@marus.com)

### **EU Authorized Representative:**

Lorna Sanderson: [lorna@mdqa.co.uk](mailto:lorna@mdqa.co.uk)  
Medical Device & QA Services Ltd,  
76, Stockport Road  
Timperley, Cheshire  
WA15 7SN  
United Kingdom  
[www.mdqa.co.uk](http://www.mdqa.co.uk)  
[info@mdqa.co.uk](mailto:info@mdqa.co.uk)  
Tel: +44 161 870 6751  
Fax: +44 161 903 9787



# marus

Marus sincerely apologizes for the inconvenience this situation causes you and your patients.

Thank you for your patience and support.

Sincerely Yours,

Bonnie Dundas  
Quality Assurance & Regulatory Affairs Manager,  
Marus